



Waimanalo photo: Cell E6 (east) repairs

Katherine Baylor to: Arlene Kabei, Steve Armann, Rich Vaille, Stephen Tyahla, Bret Moxley, Christiane Camp, Eric Magnan, Andrew Helmlinger, Dean Higuchi, Wendy Wiltse, Kahi Kahakui, Steve Wall, baylor.katherine

01/24/2011 03:15 PM

From: Katherine Baylor/R9/USEPA/US
To: Arlene Kabei/R9/USEPA/US@EPA, Steve Armann/R9/USEPA/US@EPA, Rich Vaille/R9/USEPA/US@EPA, Stephen Tyahla/R9/USEPA/US@EPA, Bret Moxley/R9/USEPA/US@EPA, Christiane Camp/R9/USEPA/US@EPA, Eric

All -

Attached please find a photo of the E6 (east) repair area. This view is looking down-canyon (approximately southwest), past the residual mud in the lower part of E6 and towards the temporary berm (upper left corner - there is a white pickup truck parked on it). The excavator is removing existing waste so that the new liner can be tied into the existing (intact) liner.

Kathy



Waimanalo012411
E6 repairs.jpg

Katherine Baylor, P.G.
U.S. Environmental Protection Agency
75 Hawthorne Street, WST-5
San Francisco, CA 94105
415-972-3351